

Details for Count of WO# - Specialty: HVAC, Status: Completed, Type: (+)

Portfolio Name	WO#	Work Description	Priority
IRAS	IRAS018837	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 3 Serenity Space DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS018835	Air Conditioning and Heating:Air Conditioning - Air Flow:Floor Level - IRAS: Level 03 Location: Meeting Room Location Number/Name: Jamming Junction Work Description: No air con	Normal
IRAS	IRAS018834	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 3 WD-U02 DESCRIBE THE PROBLEM: Hot and Stuffy	Normal
IRAS	IRAS018833	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: TD-GST-LB room on Level 20 DESCRIBE THE PROBLEM: There is no airflow in this room	Normal
IRAS	IRAS018723	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 2 Peak Medical DESCRIBE THE PROBLEM: Hot and Stuffy	Normal
IRAS	IRAS018715	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 2 Peak Medical Clinic DESCRIBE THE PROBLEM: User feedback that the doctor's room is cold but the clinic's waiting area is hot and stuffy	Normal
IRAS	IRAS018705	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 1 office next to Drop Off point. DESCRIBE THE PROBLEM: No air-con. Very warm and stuffy.	Normal
IRAS	IRAS018703	Air Conditioning and Heating:Air Conditioning - Air Flow:Floor Level - IRAS: Level 01 Location: Office Floor Location Number/Name: 01-03 Work Description: No air con. Very stuffy	Normal
IRAS	IRAS018687	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Meeting Room Location Number/Name: Codex@4 Work Description: Too warm, aircon seems like not working	Normal
IRAS	IRAS018686	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: range from table D10 to D23 DESCRIBE THE PROBLEM: the air from aircon is dusty	Normal
IRAS	IRAS018675	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 1 office beside the level 1 Lounge/Pantry DESCRIBE THE PROBLEM: The air con temperature is quite warm since yesterday.	Normal
IRAS	IRAS018640	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: 04-V03 DESCRIBE THE PROBLEM: air cond is not working.	Normal
IRAS	IRAS018557	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: Lvl 1 TXD -island Room DESCRIBE THE PROBLEM: User feedback that aircon is very cold	Normal
IRAS	IRAS018554	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: 04-V03 desk DESCRIBE THE PROBLEM: Reported aircon too warm earlier but temperature is still warm.	Normal
IRAS	IRAS018548	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: near 04-V03 desk DESCRIBE THE PROBLEM: the air temperature is too warm and it is warmer than the lift lobby.	Normal
IRAS	IRAS018546	Air Conditioning and Heating:Air Conditioning - Air Flow:Floor Level - IRAS: Level 03 Location: Office Floor Location Number/Name: 03-S01 and 03-R01 Work Description: The office aircon airflow is blowing directly toward us and it feels quite cold. Would it be possible to adjust the direction? Thank you.	Normal
IRAS	IRAS018504	Air Conditioning and Heating:Air Conditioning - Too Warm:Floor Level - IRAS: Level 13 Location: Meeting Room Location Number/Name: L13 Cowork@gov Work Description: Stuffy and warm. Room is much hotter than outside.	Normal
IRAS	IRAS017010	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Hibiscus meeting room at level 18 DESCRIBE THE PROBLEM: Reduce room temperature to 21 degrees Celsius on 03 Sep 2025 between 3.30pm (start time) to 5.00pm (end time) for 13 pax (number of meeting attendees) please	Normal
IRAS	IRAS017012	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: HRC Office Level 23 DESCRIBE THE PROBLEM: There has been renovation to the level 23 balcony. Each time the contractor open and close the door to the balcony, lots of dust was blown into the office. We hope to request for an air con	Normal
IRAS	IRAS018483	Air Conditioning and Heating:Air Quality: Lvl 2 Canteen User feedback the ventilation of the canteen is bad. Need help to check.	Normal
IRAS	IRAS018480	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: 07-01 DESCRIBE THE PROBLEM: too warm	Normal
IRAS	IRAS018477	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: VAV-11-2-26E DESCRIBE THE PROBLEM: Too warm. Please assist to arrange for site checking and let us know the before and after changes and readings.	Normal
IRAS	IRAS018464	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: Near Loop meeting room DESCRIBE THE PROBLEM: Air is directly flowing to my place	Normal
IRAS	IRAS018463	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: ISERVE level 1 DESCRIBE THE PROBLEM: aircon super hot and not on, urgent.	Normal
IRAS	IRAS018416	Air Conditioning and Heating:Air Conditioning - Extension: EXACT LOCATION(S): To extend the air-conditioning and lightings for whole of L18 including washrooms on Budget Day DATE & TIME OF AIR CON EXTENSION: Date: 12 Feb 2026 Time: To extend air-con and lightings until 11:59pm	Normal
IRAS	IRAS018408	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 19 WD 19-D01 DESCRIBE THE PROBLEM: Hot and stuffy	Normal
IRAS	IRAS017020	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: Serenity Space L3 DESCRIBE THE PROBLEM: Aircon not switching on during meeting	Normal
IRAS	IRAS018401	Air Conditioning and Heating:Air Conditioning - Air Flow:Floor Level - IRAS: Basement 01 Location: Office Floor Location Number/Name: In front of Loop meeting room Work Description: Air con directly flowing to my seat	Normal
IRAS	IRAS017022	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 1 office next to drop-off point. DESCRIBE THE PROBLEM: No air-con, very stuffy.	Normal
IRAS	IRAS017023	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: Level 1 office beside Atrium DESCRIBE THE PROBLEM: Aircon not on at this time, AGAIN	Normal
IRAS	IRAS018398	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Computer Room, Data Centre DESCRIBE THE PROBLEM: temperature high 27-28	Normal
IRAS	IRAS017025	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: Workstation C01 (Near the exit labelled Izao) DESCRIBE THE PROBLEM: The aircon outlet is blowing on my head constantly. Would like to seek assistance to tilt or narrow the outlet opening so that it will not be directly on me and the air	Normal
IRAS	IRAS017027	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: 19-E04 DESCRIBE THE PROBLEM: Cannot feel the aircon. Have put up request twice and was informed Technician came and adjusted. But no difference at all. Please go and have a feel on the cold aircon at Levels 20 and 21, then come t	Normal
IRAS	IRAS018378	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 4 WD 04-V30 DESCRIBE THE PROBLEM: Hot and stuffy	Normal
IRAS	IRAS017029	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: 19-E02 DESCRIBE THE PROBLEM: We cannot feel the air conditioning. The area is so stuffy. The technician came and showed us with his thermometer that our area is 21 degrees. Our lift lobby showed 25 degrees. The air conditioning a	Normal
IRAS	IRAS017030	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 15 WD-D09 DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS018344	Air Conditioning and Heating:Air Conditioning - Air Flow:Floor Level - IRAS: Level 23 Location: Meeting Room Location Number/Name: TYT Work Description: Tt	Normal
IRAS	IRAS018331	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: Project room DESCRIBE THE PROBLEM: The Project room is too cold. Please adjust the temperature.	Normal
IRAS	IRAS018189	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 5 Gym DESCRIBE THE PROBLEM: Air conditioning not working well. Very warm in the gym.	Normal
IRAS	IRAS018187	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 2 SVE office DESCRIBE THE PROBLEM: Hot and stuffy	Normal
IRAS	IRAS018174	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 5 Kinderland Childcare DESCRIBE THE PROBLEM: Still hot and stuffy	Normal
IRAS	IRAS018172	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: level 7 DESCRIBE THE PROBLEM: level 7 got a bad smelling Odour.	Normal
IRAS	IRAS018166	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 5 Kinderland Childcare DESCRIBE THE PROBLEM: Hot and stuffy	Normal
IRAS	IRAS017038	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: Jamming Junction Meeting Room has no airflow DESCRIBE THE PROBLEM: No aircon/airflow in the room	Normal
IRAS	IRAS018161	Air Conditioning and Heating:Air Conditioning - Too Cold:Floor Level - IRAS: Level 03 Location: Office Floor Location Number/Name: ACR office Work Description: Aircon is too cold. Overall around 21 to 22 degrees. Kindly adjust to 24 degrees	Normal
IRAS	IRAS018156	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: B1 Discovery Room DESCRIBE THE PROBLEM: Hot and stuffy	Normal
IRAS	IRAS018149	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 3 Serenity DESCRIBE THE PROBLEM: Hot and stuffy	Normal
IRAS	IRAS018143	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: ACR office level 3 DESCRIBE THE PROBLEM: Aircon is too cold, 21.1 degrees. Please adjust the temperature to 24 degrees for VAV-3-5-1E & VAV-3-5-25E. Thanks.	Normal
IRAS	IRAS018142	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: Lvl 2 SVE Experience DESCRIBE THE PROBLEM: aircon too cold	Normal
IRAS	IRAS018135	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: L15 office DESCRIBE THE PROBLEM: Aircon too cold	Normal
IRAS	IRAS018097	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: Revenue House B1 near ENGAGE Meeting room DESCRIBE THE PROBLEM: Air Conditioning is so cold	Normal
IRAS	IRAS018089	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: Director pt-vsd office. DESCRIBE THE PROBLEM: Aircon is too cold. Average temperature is about 20 deg	Normal
IRAS	IRAS018075	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 16, please turn right after exit the lift. DESCRIBE THE PROBLEM: Once turn right after exit the life, that entire location is the specific location where users feedback it is very stuffy and hot.	Normal
IRAS	IRAS017997	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 5 Clubhouse Gym DESCRIBE THE PROBLEM: Aircon warm - need top up gas	Normal
IRAS	IRAS017932	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: 19-D08 DESCRIBE THE PROBLEM: No airflow; extremely warm and stuffy	Normal
IRAS	IRAS017930	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 19 WD-D01 DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017877	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Auditorium DESCRIBE THE PROBLEM: Very warm. Aircon not working?	Normal
IRAS	IRAS017828	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: 04-P07 area DESCRIBE THE PROBLEM: Black dust particles falling from the aircon vents onto work desk every morning. It is very dusty and messy.	Normal
IRAS	IRAS017786	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 5 Kinderland DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017784	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Harmony@B1 DESCRIBE THE PROBLEM: Too warm	Normal
IRAS	IRAS017071	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: CIR's office DESCRIBE THE PROBLEM: Too cold.	Normal
IRAS	IRAS017744	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 19, Area around desk 19-D07 DESCRIBE THE PROBLEM: Air con temperature is 26.9 degrees	Normal
IRAS	IRAS017736	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 3 Kinderland DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017730	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: Tax Academy at #B1-01 DESCRIBE THE PROBLEM: Air is still, pls increase fan speed.	Normal
IRAS	IRAS017724	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Courage@B1 DESCRIBE THE PROBLEM: Air cond is too warm. We are having meeting but everyone is sweating.	Normal
IRAS	IRAS017725	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl B1 Discovery Room DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017724	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: Unity@21 DESCRIBE THE PROBLEM: Aircon not on	Normal
IRAS	IRAS017721	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Basement 1 DESCRIBE THE PROBLEM: Book discovery and courage room at basement 1 and no aircon at all	Normal
IRAS	IRAS017668	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: B1-Growth DESCRIBE THE PROBLEM: no power	Normal
IRAS	IRAS017663	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: AHU 10-1 DESCRIBE THE PROBLEM: The area is warm which is served by AHU 10-1. Please help to check if there is any issue. Recorded avg ambient temp is at 25.3	Normal
IRAS	IRAS017653	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: Vent above 21-M02 DESCRIBE THE PROBLEM: Aircon too cold	Normal
IRAS	IRAS017650	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 17 WD-F02 DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017648	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 23 WD-G02 DESCRIBE THE PROBLEM: Hot and Stuffy	Normal
IRAS	IRAS017645	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: L3 DESCRIBE THE PROBLEM: User reported her office room is very cold, kindly assist asap as she feedback that she had reported previously but still the same.	Normal
IRAS	IRAS017640	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl B1 Growth Meeting Room DESCRIBE THE PROBLEM: User say hot and stuffy	Normal
IRAS	IRAS017099	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 23 - EGM DESCRIBE THE PROBLEM: Office seems a bit stuffy. No air flow and temperature seems a bit too warm	Normal
IRAS	IRAS017638	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: L19-C09 DESCRIBE THE PROBLEM: Too warm and air flow is not optimal	Normal
IRAS	IRAS017636	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: RH Level 2 IT Support Room DESCRIBE THE PROBLEM: Aircon not working, room temperature very hot and stuffy since yesterday. Request to disseminate the air flow of the air-con evenly. (Urgent)	Normal
IRAS	IRAS017631	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: DC's office DESCRIBE THE PROBLEM: too warm	Normal
IRAS	IRAS017617	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: SINGAPORE CUSTOMS, LEVEL 7 @ INTERNATIONAL RELATIONS BRANCH AREAS,@Esther Ng@Valerie Tan DESCRIBE THE PROBLEM: The aircon air flow not equally distribution. Those areas are affected, No air con is strong. The areas are h	Normal
IRAS	IRAS017612	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: IFD Office - Field Team Office DESCRIBE THE PROBLEM: Aircon fan is too low. The circulation is not strong.	Normal
IRAS	IRAS017604	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Growth@B1 DESCRIBE THE PROBLEM: The air cond is still warm in the room. It is still hovering between 24.5 to 25 degree in the room, and the air is stuffy toward the projector area.	Normal
IRAS	IRAS017600	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Growth@B1 DESCRIBE THE PROBLEM: The air cond is still very warm. The room is stuffy especially near to the projector area. Please make the adjustment. Thanks.	Normal
IRAS	IRAS017596	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Growth@B1 DESCRIBE THE PROBLEM: Air cond is still too warm. The corridor is even colder than inside.	Normal
IRAS	IRAS017108	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Hibiscus meeting room at level 18 DESCRIBE THE PROBLEM: Sorry for the last minute request. Reduce room temperature to 21 degrees Celsius on 08 Sep 2025 between 3pm (start time) to 6pm (end time) for 14 pax please	Normal
IRAS	IRAS017592	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: Level 3 CSS Branch, Suzanne's room DESCRIBE THE PROBLEM: 1. Air con not cold 2. Dirt	Normal
IRAS	IRAS017583	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Growth@B1 DESCRIBE THE PROBLEM: The air con had become too warm. The air in the room is very stuffy.	Normal
IRAS	IRAS017563	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: level 6 and level 7 DESCRIBE THE PROBLEM: air conditioning too warm	Normal
IRAS	IRAS017559	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 3 WD-002 DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017558	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 3 DESCRIBE THE PROBLEM: Learning north meeting room aircon not on	Normal
IRAS	IRAS017548	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 7-01 DESCRIBE THE PROBLEM: room is too warm	Normal
IRAS	IRAS017544	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: ACR office. VAV-3-5, VAV-3-7, and VAV-3-8 DESCRIBE THE PROBLEM: Most of ACR office is poorly ventilated except for Pantry. Please increase the airflow for all the valve. thank you	Normal
IRAS	IRAS017543	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 18 workstation Q02 DESCRIBE THE PROBLEM: Air con too warm.	Normal
IRAS	IRAS017520	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 15 DESCRIBE THE PROBLEM: Not cold / no aircon flow	Normal
IRAS	IRAS017505	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 19 WD-C03 DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017500	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 07 DESCRIBE THE PROBLEM: the aircon at level 7 warm	Normal
IRAS	IRAS017498	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 18 InTp DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017491	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: L19-C09 DESCRIBE THE PROBLEM: Office is too warm. Please improve airflow for aircon. Thanks	Normal
IRAS	IRAS017125	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: Level 5 Clubhouse Aircon DESCRIBE THE PROBLEM: Airflow is fine, but numbers on Aircon controller is blinking.	Normal
IRAS	IRAS017480	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 21 WD-Y02 DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017477	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: ACR L3 office DESCRIBE THE PROBLEM: VAV-03-05-03E temperature is 24.9degrees. Kindly adjust it to 23degrees. Thanks	Normal
IRAS	IRAS017447	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: level 19-N08 DESCRIBE THE PROBLEM: Area around workstation 19-N08 is very warm. In general, the whole floor at level 19 is quite warm. This is in stark contrast to floors like level 4 or level 23 where the aircon temperature is much l	Normal
IRAS	IRAS017438	Air Conditioning and Heating:Air Conditioning - Too Cold:CONFIRM SPECIFIC LOCATION: Lvl 1 Near the RPA Lab DESCRIBE THE PROBLEM: aircon too cold	Normal
IRAS	IRAS017431	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Growth@B1 DESCRIBE THE PROBLEM: The aircon is too warm even though it has been turned on for some time.	Normal
IRAS	IRAS017131	Air Conditioning and Heating:Air Conditioning - Extension: EXACT LOCATION(S): Entire level 15 DATE & TIME OF AIR CON EXTENSION: 14 Sep 2025 8am to 3pm	Normal
IRAS	IRAS017408	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: 19-D01 DESCRIBE THE PROBLEM: It is very warm. Like no air-con and no air flow.	Normal
IRAS	IRAS017375	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: Tax Academy office at #B1-01. DESCRIBE THE PROBLEM: Little airflow.	Normal
IRAS	IRAS017373	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 3 ACR office DESCRIBE THE PROBLEM: Staff complained that there is no airflow at the VAV-03-08-12E area. Kindly adjust the airflow stronger. Thanks	Normal
IRAS	IRAS017365	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: E13 DESCRIBE THE PROBLEM: Air conditioning has been way too warm recently	Normal
IRAS	IRAS017363	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 19-N08 area DESCRIBE THE PROBLEM: Very stuffy and warm	Normal
IRAS	IRAS017321	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Near Ruby@19 Meeting Room DESCRIBE THE PROBLEM: Temperature is more than 25°C, especially in the morning.	Normal
IRAS	IRAS017320	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 18 @ Daffodil DESCRIBE THE PROBLEM: No aircon. No aircon. The technician has come in the morning. But the aircon is still not working. If cannot fix, can bring in the standing fan. Thanks	Normal
IRAS	IRAS017318	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Daffodil DESCRIBE THE PROBLEM: No aircon. If cannot fix, can bring a standing fan.	Normal
IRAS	IRAS017313	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: L2 SVE area workstation G07 DESCRIBE THE PROBLEM: Aircon hot & stuffy	Normal
IRAS	IRAS017307	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 2, SVE office. Harness Room (near pantry) DESCRIBE THE PROBLEM: Aircon seems to be completely off. Need help to turn it on and make the room cooler urgently. Meeting ongoing. Thanks!	Scheduled
IRAS	IRAS017305	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: Daffodil Room @ L18 DESCRIBE THE PROBLEM: No aircon	Normal
IRAS	IRAS017304	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 3 Jamming Junction DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017303	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: CIR's room DESCRIBE THE PROBLEM: no aircon	Normal
IRAS	IRAS017302	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: CIR's office DESCRIBE THE PROBLEM: Aircon doesn't seem to be working	Normal
IRAS	IRAS017296	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 5 MPH DESCRIBE THE PROBLEM: Hot and stuffy Jmpree booking was at 8am-6pm	Normal
IRAS	IRAS017295	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: L2-G13 area/SVE temp staff side DESCRIBE THE PROBLEM: Aircon Hot & Stuffy	Normal
IRAS	IRAS017293	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: L14 VAV 14-2-27 DESCRIBE THE PROBLEM: Please assist to increase airflow. Staff feedback very warm. Please confirm the Vav% before and after.	Normal
IRAS	IRAS017147	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: L13 newly constructed SO room DESCRIBE THE PROBLEM: L13 VAV 13-01-01N for the room is warm and stuffy, please check onsite	Normal
IRAS	IRAS017292	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 22 ItAR Office close door DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017289	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 24 Conference DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017281	Air Conditioning and Heating:Air Conditioning - Noise:CONFIRM SPECIFIC LOCATION: Level b1 lounge area aircon DESCRIBE THE PROBLEM: HI, we have filming and videography event on 30 Sep Tuesday 8am - 6pm and we would like to request aircon to have no noise during videography filming. thank you	Normal
IRAS	IRAS017259	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Income Tax Policy (InTP) Branch, Level 18 DESCRIBE THE PROBLEM: The air-con too warm and room feeling stuffy. Currently highest reading is 27.5 degree Celsius. Please assist. Thanks.	Normal
IRAS	IRAS017257	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: 18-Q07 DESCRIBE THE PROBLEM: No Aircon	Normal
IRAS	IRAS017251	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: SVE level 2 office, Innovate Room DESCRIBE THE PROBLEM: Aircon temperature is too warm at 28. Need help to make it colder. Thanks!	Normal
IRAS	IRAS017249	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: 18-Q07 DESCRIBE THE PROBLEM: no aircon	Normal
IRAS	IRAS017237	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Near Workstation HD 23-W01 DESCRIBE THE PROBLEM: No air flow (stuffy). Feel warm.	Normal
IRAS	IRAS017234	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Lvl 2 SVE Innovate Room DESCRIBE THE PROBLEM: hot and stuffy	Normal
IRAS	IRAS017229	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: L2C-B01 DESCRIBE THE PROBLEM: Aircon not cold enough	Normal
IRAS	IRAS017219	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: Level 5 Clubhouse (Office, Dance studio, and Room 11 aircon) DESCRIBE THE PROBLEM: Aircon control panels are flashing UO sign.	Normal
IRAS	IRAS017218	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: B1 Courage and discovery room DESCRIBE THE PROBLEM: Air Con too warm	Normal
IRAS	IRAS017214	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: Level 16 DESCRIBE THE PROBLEM: Users feedback that the aircon is very warm.	Normal
IRAS	IRAS017194	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: L12 VAV 12-01-08 DESCRIBE THE PROBLEM: Previously reduced VAV from 70 to 40%. Refer to IRAS016850. Please put at 50%. Do provide before and after photo. Thank you.	Normal
IRAS	IRAS017163	Air Conditioning and Heating:Air Conditioning - Noise:CONFIRM SPECIFIC LOCATION: B1 Engage DESCRIBE THE PROBLEM: Very loud noise in the meeting room.	Normal
IRAS	IRAS017187	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: level 5 MPH DESCRIBE THE PROBLEM: 90c (thru): to turn on aircon at 8am for event in MPH	Normal
IRAS	IRAS017183	Air Conditioning and Heating:Air Conditioning - Too Warm:CONFIRM SPECIFIC LOCATION: level 5 auditorium DESCRIBE THE PROBLEM: wed 80c: to turn on aircon at 8am to cool down venue for event and to ensure sufficient airflow, based on past experience, auditorium was warm when it was filled	Normal
IRAS	IRAS017181	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: level 5 auditorium DESCRIBE THE PROBLEM: turn on aircon at 8am for event on tues, 70c. based on past experience, ambient temperature in auditorium is warm once auditorium is filled up	Normal
IRAS	IRAS017179	Air Conditioning and Heating:Air Conditioning - Air Flow:CONFIRM SPECIFIC LOCATION: level 5 auditorium DESCRIBE THE PROBLEM: to start the aircon at 12pm til 6pm on 6Oct monday	