


Technical Briefing Chassis & Engine Number Identifier

12 September 2019



Problem statement

To accurately assess physical chassis and engine number for the purpose of tampered vehicle investigation (i.e. tampering of chassis and engine number)

Challenge

Currently, there are instances where investigation to the physical vehicle chassis and engine number tampering cases are affected as these numbers could not be verified.



Tampered Engine Number (Grinded Surface)




Original Surface

Blocked engine number



Location



Blocked by wiring and pipe

Blocked engine number



Location



Blocked by firewall

Burnt by engine component



Product evaluation criteria

A portable system/device that is able to read the physical engine/chassis numbers. Such system shall be compatible with most vehicle models (if not all) in the market.

| Evaluation Criterion | Weightage (%) |
|---|---------------|
| 1. Technical feasibility of solution | 30 |
| 2. Innovation | 20 |
| 3. Economic Feasibility and Commercialization Potential (Include development cost and final product cost) | 30 |
| 4. Capacity and Expertise to Execute Project | 20 |
| Total Score | 100 |


T CT STATE

SGWBUS O

0

Er in

- Quint



æ

4

y

www.lta.gov.sg

LTAsg

WeKeepYourWorldMoving

END